

AD-A104 665

ARMY ENGINEER DISTRICT ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM, ANDERSON LAKE DAM (MO 30410), MISS--ETC(U)
DEC 78 A L JOHNSON

F/6 13/13

UNCLASSIFIED

NL

1 OF 1
ADA
104665

END
DATE
FILMED
10-81
DTIC

AD A104665

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A104665	
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Anderson Lake Dam (MO 30410) Jefferson County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Corps of Engineers, St. Louis District		6. PERFORMING ORG. REPORT NUMBER
		8. CONTRACT OR GRANT NUMBER(s) N/A
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		12. REPORT DATE December 1978
		13. NUMBER OF PAGES Approximately 45
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) National Dam Safety Program, Anderson Lake Dam (MO 30410), Mississippi- Kaskaskia-St. Louis Basin, Jefferson County, Missouri, Phase I		15. SECURITY CLASS. (of this report) UNCLASSIFIED DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION Inspection Report. Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		


DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with ... translation of (or by) ... Presented at conference of ... To be published in ...

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

ANDERSON LAKE DAM
JEFFERSON COUNTY, MISSOURI
MISSOURI INVENTORY NO. 30410

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

PREPARED BY: ST. LOUIS DISTRICT CORPS OF ENGINEERS
FOR: GOVERNOR OF MISSOURI

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

Name of Dam: Anderson Lake Dam
State Located: Missouri
County Located: Jefferson County
Stream: No Name
Date of Inspection: 7 September 1978

Anderson Lake Dam was inspected by an interdisciplinary team of engineers from the St. Louis District, U. S. Army Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property. The inspection and assessment were made using the "Recommended Guidelines for Safety Inspection of Dams" developed by the Chief of Engineers, U.S. Army, Washington, DC, with the help of several Federal and state agencies, professional engineering organizations and private engineers.

Based on these guidelines, this dam is classified as a small size dam with a high downstream hazard potential. Failure would threaten the life and property of approximately four families downstream of the dam and cause appreciable damage to one farm complex, one improved road and two unimproved roads, all within a three-mile damage reach of the lake.

For its size and hazard category, this dam is required by the guidelines to pass from one-half PMF to PMF. However, considering the high-hazard potential to life (four residences) and property downstream of the dam, the PMF is considered the appropriate spillway design flood. Since the spillway for the dam is not capable of passing a minimum of one-half (50 percent) of the PMF without overtopping the dam and causing failure, the spillway is considered seriously inadequate. The spillway is capable of passing 20 percent of the PMF without overtopping the dam.

Other deficiencies visually observed by the inspection team were a thick cover of trees and brush on both sides of the embankment slopes, lack of erosion protection from runoff on the downstream face of the left abutment, lack of erosion protection along the spillway channel and the upstream face of the embankments, and the exit channel flows along the toe of the embankment. Another

deficiency which should be corrected was the lack of seepage and stability analyses comparable to the requirements of the guidelines. However, none of these deficiencies present a serious threat to the dam's stability.

It is recommended that the owner take action to correct or control the deficiencies described. A detailed report discussing each of these deficiencies was prepared and submitted herewith.

Sar. Lynne E. Puetz P.E.
LYNNE E. PUETZ
Hydraulic Engineer
St. Louis District
Corps of Engineers

Joseph L. Schwenk
JOE SCHWENK
Soils Engineer
St. Louis District
Corps of Engineers

Michael J. Klosterman
MICHAEL J. KLOSTERMAN
Geologist
St. Louis District
Corps of Engineers

SUBMITTED BY: William L. Johnson 20 Dec 78
for Chief, Engineering Division Date

APPROVED BY: Leon E. Mills 20 Dec 78
Colonel, CE, District Engineer Date

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
ANDERSON LAKE DAM - ID NO. 30410

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	2
SECTION 2 - ENGINEERING DATA		
2.1	Design	5
2.2	Construction	5
2.3	Operation	5
2.4	Evaluation	5
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	6
3.2	Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	8
4.2	Maintenance of Dam	8
4.3	Maintenance of Operating Facilities	8
4.4	Description of Any Warning System in Effect	8
4.5	Evaluation	8
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	9
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	10
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	11
7.2	Remedial Measures	11
APPENDIX		
A	Hydrologic Computations	

TABLE OF CONTENTS (Continued)

LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Location Map
2	Vicinity Topograph
3	Plan
4	Dam Profile and Cross Section

LIST OF PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
1	Upstream View of Lake
2	Downstream Face of Dam
3	Downstream Face of Dam and Spillway
4	Upstream Face of Right Abutment and Spillway
5	Downstream View of Spillway
6	Upstream View of Spillway
7	Seepage Near Right Abutment, Downstream Face of Embankment
8	Exit Channel Running Along Toe of Dam



VIEW FROM THE OBSERVATION PLATFORM

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
ANDERSON LAKE DAM - ID NO. 30410

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of the Anderson Lake Dam be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many State agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances.

(1) The dam is an earth structure built in a narrow valley. The topography adjacent to the valley is rolling to steep. The earth embankment is composed of brown silty clay. Topography in the vicinity of the dam is shown on PLATE 2.

(2) The spillway, located on the right abutment, was cut in sedimentary rock. There are no outlet works or other structures controlling releases from the lake except for the spillway.

(3) Pertinent physical data are given in paragraph 1.3 below.

b. Location: The dam is located in the southwestern portion of Jefferson County, Missouri, as shown on PLATE 1. The lake formed by the dam is located in the SW 1/4 of Section 7 of T40N, R4E of the Fletcher, Missouri Quadrangle Sheet.

c. Size Classification: Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, this dam and impoundment is in the small size category.

d. Hazard Classification: Guidelines for determining hazard classification are presented in the same guidelines as referenced in paragraph 1.2c, above. Based on referenced guidelines, this dam is in the High Hazard Classification

e. Ownership. This dam is owned by Mr. Hugh Anderson.

f. Purpose of Dam. The dam forms a 5.2-acre recreational lake.

g. Design and Construction History. It was reported that the dam was built in 1958 by the previous owner. Plans for the construction of the dam were prepared but the present owner was unable to locate the design plans. The location of the previous owner is not known.

h. Normal Operating Procedure. No operating records exist. Outflow passes over an uncontrolled spillway.

1.3 PERTINENT DATA

a. Drainage Area - 93 acres

b. Discharge at Damsite: Not known

Maximum known flood at damsite - 1 foot depth over spillway reported

Spillway capacity at maximum pool elevation - 350 cfs

c. Elevation (feet Above m.s.l. from assumed benchmark of 700 ft. m.s.l.):

(1) Top of dam - 699.2

(2) Flood control pool - 699.2

- (3) Recreation pool - 696.8
- (4) Streambed - 673+
- (6) Maximum tailwater - Not known

d. Reservoir:

Length of maximum pool - Approximately 1,200 feet

Length of recreation pool - Approximately 900 feet

e. Storage (Acre-feet):

Recreation pool - 57

Flood Control pool - 68

Design surcharge - 0

Top of dam - 68

f. Reservoir Surface Area (Acres):

Top of dam - 5.2

Maximum pool - 5.2

Flood control pool - 5.2

Recreation pool - 4.7

Spillway crest - 4.7

g. Dam.

Type - Earth fill.

Length - 335 feet.

Height - 26+ feet

Top width - 10 feet.

Side Slopes - Varies, typically 1 vertical on 1.5 horizontal downstream; upstream side slope could not be determined. A typical section is shown on PLATE 4.

Zoning - Unknown.

Impervious Core - Unknown.

Cutoff - Unknown.

Grout curtain - Unknown.

h. Diversion and Regulating Tunnel: None.

i. Spillway.

- (1) Type - Earth/rock channel
- (2) Length of weir - Not applicable
- (3) Crest elevation - 696.8

j. Regulating Outlets. None

SECTION 2 - ENGINEERING DATA

2.1 DESIGN.

No design data were found to be readily available.

2.2 CONSTRUCTION.

The dam was built in 1958 by the previous owner. Plans for the construction of the dam were prepared but the present owner was unable to locate the design plans. The location of the previous owner is not known.

2.3 OPERATION.

The maximum reservoir loading on the dam is not known. All releases are through an uncontrolled spillway

2.4 EVALUATION.

a. Availability. No design or construction data were available.

b. Adequacy. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dam" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for the appropriate loading conditions and made a matter of record.

c. Validity. No valid engineering design data of construction data were available.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General. A visual inspection of the dam, outlet spillway and exit channel was made on 7 September 1978 by Corps of Engineers, St. Louis District personnel. The owner, Mr. Anderson, accompanied the inspection team. Very little information was available concerning construction of the dam.

b. Project Geology.

(1) The Anderson Lake Dam and drainage area is underlain by the Ordovician Jefferson City formation. Bedrock exposed in the spillway is light brown to cream, fine grained, thinly bedded dolomite with a moderately spalled surface. The bedding is essentially horizontal. The rock surface was slightly jointed by a set of short, closely spaced, relatively tight NW-SE trending joints. The bedrock exposed in the spillway was the only rock outcrop found in the entire drainage area, the remainder being covered by thin, cherty Jefferson City-Cotter residuum.

(2) The dam is located approximately 3 miles northeast of the northern edge of the Valle Mines - Vineland fault zone. The last major movement along this fault zone has been described as being post-Ordovician (440 million years before present), and it is not considered to be active. No evidence of faulting or other tectonic activity was observed in the area of the dam.

(3) No evidence of karst or other solution activity was found in the drainage area. On the right abutment, a small amount of water was observed seeping from the rock-embankment interface at the downstream edge of the spillway near the toe of the dam. On the left abutment, a small springhouse was located approximately 50 feet downstream of the toe of the dam; however, no artesian flow was apparent.

c. Dam.

(1) The dam is an earth embankment composed of brown silty clay. The dam is heavily vegetated and has scattered trees 3 inches in diameter and less growing on the downstream slope. The upstream slope is covered with willow trees that are less than 3 inches in diameter. These root systems constitute a potential seepage hazard. The crown has thick grass cover and is occasionally mowed. No detrimental settlement, cracking or sinkholes were observed in or near the earth embankment.

(2) No animal burrows were noted in the embankment. However, the thick vegetation provides animal habitat which increases the likelihood of animal burrows.

(3) No riprap exists on the upstream slope of the dam. However very little erosion has taken place on the upstream slope due to wave action.

(4) The downstream slope varies, typically 1 vertical on 1.5 horizontal. The upstream slope could not be determined.

(5) Marshy areas with standing water were observed approximately 25 feet downstream of the toe of the dam. A spring was observed seeping from the rock outcrop located at the right abutment of the dam.

(6) Surface drainage from the left side of the lake has caused minor erosion near the left abutment and dam embankment. Gullies were observed to be 8 inches deep. Erosion of the downstream slope of the dam is very minimal, if any.

d. Appurtenant Structures. The only appurtenant structure was the spillway which discharges over a series of rock falls to reach the original channel. No obstructions were observed in the spillway area and growth of vegetation is very minimal.

e. Reservoir Area. No pertinent problems were noted in any of the reservoir area.

f. Downstream Channels. The downstream channel has a marshy area with brush and trees growing along the downstream channel.

3.2 EVALUATION.

None of the conditions observed on the dam pose a serious threat to its stability. Maintenance of the downstream and upstream slope should be performed to discourage animal burrowing and to eliminate tree-root systems both of which could lead to seepage problems.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES.

There are no controlled outlet works for this dam; therefore, no regulating procedures exist. The pool is controlled by rainfall, runoff, evaporation, and capacity of the uncontrolled spillway.

4.2 MAINTENANCE OF DAM.

Based on the amount of brush and size of trees on the upstream and downstream slopes, it has been several years since the vegetation has been cut.

4.3 MAINTENANCE OF OPERATING FACILITIES.

No operating facilities exist.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT.

The inspection team is not aware of any existing warning system for this dam.

4.5 EVALUATION.

If the uncontrolled vegetation on the slopes are allowed to continue, potential problems may develop.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES.

a. Design Data: No design data were made available to the inspection team. All releases are nonregulated.

b. Experience Data: All of the pertinent data furnished in this report were derived from U. S. Geological Survey 7½ Minute Quadrangle Sheets or from measurements and surveys made during this inspection.

c. Visual Observations:

(1) A spring was observed seeping from the rock outcrop located at the right abutment of the dam.

(2) Trees and brush are growing on the dam embankment.

d. Overtopping Potential:

(1) The spillway is too small to pass the minimum required flood of one-half of the Probable Maximum Flood (PMF) without overtopping. The PMF is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The spillway is capable of passing 20 percent of the PMF without overtopping. Routing 50 percent of the PMF through the reservoir indicated the dam will be overtopped by a flow of 900 cfs at a depth of .7 foot for approximately 45 minutes. The PMF would result in an overtopping flow of 2,100 cfs, a depth of 1.3 feet for a duration of five hours.

(2) The effects from rupture of the dam could extend approximately three miles downstream of the dam. There are three houses and one mobile home immediately downstream of the dam in addition to a group of farm buildings, one improved road crossing and two unimproved crossings within three miles of the dam. Should failure of the dam occur, these buildings could be severely damaged and the lives of any inhabitants lost.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY.

a. Visual Observations. Visual observations of conditions which adversely affect the structural stability of this dam are discussed in Section 3.

b. Design and Construction Data. No design or construction data relating to the structural stability of the dam were found available. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Operating Records. No appurtenant structures requiring operation exist at this dam.

d. Post Construction Changes. No post construction changes were reported.

e. Seismic Stability. The dam is located in seismic zone 2, for which the recommended guidelines assign a "moderate" damage probability. Since detailed information on the properties of the materials in the embankment is not available, an accurate seismic evaluation cannot be made. The clayey materials used in the embankment minimize the likelihood of failure due to an earthquake.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT.

a. Safety. Several items are deficient which should be corrected. No erosion protection exists on the upstream slope of the dam. Erosion protection should be provided in the area of downstream slope of the left abutment. Exit channels are not sufficiently protected against erosion. Trees and bushes on the embankments provide a potential seepage hazard and animal habitat.

b. Adequacy of Information. The statements and recommendations in this report are based on visual observations and verbal discussions. Seepage and stability analyses are not on record as prescribed in the recommended guidelines.

c. Urgency. It is recommended that the remedial measures listed in Section 7.2 be accomplished in the near future.

d. Need for Phase II. No Phase II inspection is recommended. Action should begin on the remedial actions discussed in this report.

7.2 REMEDIAL MEASURES.

The following remedial measures are recommended:

a. Remove trees and cut-bushes on the upstream and downstream slopes and reestablish with grass cover. Holes created by the removal of trees should be suitably backfilled.

b. Fill any animal burrows found during clearing.

c. Spillway size and/or height of dam should be increased to pass the probable maximum flood without overtopping the dam.

d. Provide erosion protection from surface runoff at the left abutment and downstream slope.

e. Realine the exit channel to direct flow from the toe of the embankment.

f. A stability and seepage analysis of the dam should be performed by a professional engineer experienced in the design and construction of dams.

APPENDIX A
HYDROLOGIC COMPUTATIONS

HYDROLOGIC AND HYDRAULIC ANALYSIS METHODOLOGY

1. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for a reservoir routing. The Probable Maximum Precipitation is derived and determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33." Reduction factors have not been applied. A 24-hour storm duration is assumed with the total rainfall depth distributed over 6-hour periods in accordance with procedures outlined in EM 1110-2-1411 (SPF Determination). The maximum 6-hour rainfall period is then distributed to hourly increments by the same criteria. Within-the-hour distribution is based upon NOAA Technical Memorandum NWS HYDRO-35. The non-peak 6-hour rainfall periods are distributed uniformly. All distributed values are arranged in a critical sequence by the SPF criteria. The final inflow hydrograph is produced by deduction of infiltration losses appropriate to the soil, land use, and antecedent moisture conditions.
2. The reservoir routing is accomplished by using Modified Puls routing techniques wherein the flood hydrograph is routed through lake storage. Hydraulic capacities of the spillway, and crest of dam are used as outlet controls in the routing. Storage in the pool area is defined by an elevation-storage capacity curve. The hydraulic capacity of the outlet works, spillway, and top of dam are defined by elevation-discharge curves.
3. Dam overtopping analysis has been conducted by hydrologic methods for this dam and lake. This computation determines the percentage of the PMF hydrograph that the reservoir can contain without the dam being overtopped. An output summary in the hydrologic appendix displays this information as well as other characteristics of the simulated dam overtopping.
4. The above analysis has been accomplished for this report using the systemized computer program HEC-1 (Dam Safety Version), July 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. The numeric parameters estimated for this site are listed in the attached computer printout. Definitions of these variables are contained in the "User's Manual" for the computer program.

[illegible]

100-44388-100

$\log_{10} \text{TPP} = -0.0067 + 0.0009 \text{TPP}$

[illegible][illegible]

ID	L1000-1-FC1000-1100					L1000-1-FC1000-1100					L1000-1-FC1000-1100					L1000-1-FC1000-1100				
	PKLFC	PKRTP	RATD	L1CS	L0CS	COFC	COFC	COFC	COFC	COFC	PKLFC	PKRTP	RATD	L1CS	L0CS	COFC	COFC	COFC	COFC	COFC
1	1.01	1.05	1.01	1.00	.01	0.	1.01	12.05	145	.21	.20	.01	175.							
2	1.01	1.10	.01	0.00	.01	0.	1.01	12.10	146	.24	.20	.01	175.							
3	1.01	1.15	.01	0.00	.01	0.	1.01	12.15	147	.21	.20	.01	221.							
4	1.01	1.20	.01	0.00	.01	0.	1.01	12.20	148	.21	.20	.01	231.							
5	1.01	1.25	.01	0.00	.01	0.	1.01	12.25	149	.21	.20	.01	235.							
6	1.01	1.30	.01	0.00	.01	0.	1.01	12.30	150	.21	.20	.01	237.							
7	1.01	1.35	.01	0.00	.01	0.	1.01	12.35	151	.21	.20	.01	238.							
8	1.01	1.40	.01	0.00	.01	0.	1.01	12.40	152	.21	.21	.01	231.							
9	1.01	1.45	.01	0.00	.01	0.	1.01	12.45	153	.21	.21	.01	235.							
10	1.01	1.50	.01	0.00	.01	0.	1.01	12.50	154	.21	.21	.01	230.							
11	1.01	1.55	.01	0.00	.01	0.	1.01	12.55	155	.21	.21	.01	235.							
12	1.01	1.60	.01	0.00	.01	0.	1.01	13.00	156	.21	.21	.01	260.							
13	1.01	1.65	.01	0.00	.01	0.	1.01	13.05	157	.26	.25	.01	256.							
14	1.01	1.70	.01	0.00	.01	0.	1.01	13.10	158	.26	.25	.01	271.							
15	1.01	1.75	.01	0.00	.01	0.	1.01	13.15	159	.26	.25	.01	215.							
16	1.01	1.80	.01	0.00	.01	0.	1.01	13.20	160	.26	.25	.01	270.							
17	1.01	1.85	.01	0.00	.01	0.	1.01	13.25	161	.26	.25	.01	270.							
18	1.01	1.90	.01	0.00	.01	0.	1.01	13.30	162	.26	.25	.01	200.							
19	1.01	1.95	.01	0.00	.01	0.	1.01	13.35	163	.26	.25	.01	200.							
20	1.01	2.00	.01	0.00	.01	0.	1.01	13.40	164	.26	.25	.01	200.							
21	1.01	2.05	.01	0.00	.01	0.	1.01	13.45	165	.26	.25	.01	251.							
22	1.01	2.10	.01	0.00	.01	0.	1.01	13.50	166	.21	.25	.01	201.							
23	1.01	2.15	.01	0.00	.01	0.	1.01	13.55	167	.26	.25	.01	211.							
24	1.01	2.20	.01	0.00	.01	0.	1.01	14.00	168	.26	.25	.01	211.							
25	1.01	2.25	.01	0.00	.01	0.	1.01	14.05	169	.32	.31	.01	316.							
26	1.01	2.30	.01	0.00	.01	0.	1.01	14.10	170	.32	.31	.01	347.							
27	1.01	2.35	.01	0.00	.01	0.	1.01	14.15	171	.32	.31	.01	352.							
28	1.01	2.40	.01	0.00	.01	0.	1.01	14.20	172	.32	.31	.01	352.							
29	1.01	2.45	.01	0.00	.01	0.	1.01	14.25	173	.32	.31	.01	352.							
30	1.01	2.50	.01	0.00	.01	0.	1.01	14.30	174	.32	.31	.01	352.							
31	1.01	2.55	.01	0.00	.01	0.	1.01	14.35	175	.32	.31	.01	352.							
32	1.01	2.60	.01	0.00	.01	0.	1.01	14.40	176	.32	.32</									

Year	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																								
Population (millions)	7.0	7.1	7.2	7.3	7.4	7.5	7.6	7.7	7.8	7.9	8.0	8.1	8.2	8.3	8.4	8.5	8.6	8.7	8.8	8.9	9.0	9.1	9.2	9.3	9.4	9.5	9.6	9.7	9.8	9.9	10.0	10.1	10.2	10.3	10.4	10.5	10.6	10.7	10.8	10.9	11.0	11.1	11.2	11.3	11.4	11.5	11.6	11.7	11.8	11.9	12.0	12.1	12.2	12.3	12.4	12.5	12.6	12.7	12.8	12.9	13.0	13.1	13.2	13.3	13.4	13.5	13.6	13.7	13.8	13.9	14.0	14.1	14.2	14.3	14.4	14.5	14.6	14.7	14.8	14.9	15.0	15.1	15.2	15.3	15.4	15.5	15.6	15.7	15.8	15.9	16.0	16.1	16.2	16.3	16.4	16.5	16.6	16.7	16.8	16.9	17.0	17.1	17.2	17.3	17.4	17.5	17.6	17.7	17.8	17.9	18.0	18.1	18.2	18.3	18.4	18.5	18.6	18.7	18.8	18.9	19.0	19.1	19.2	19.3	19.4	19.5	19.6	19.7	19.8	19.9	20.0	20.1	20.2	20.3	20.4	20.5	20.6	20.7	20.8	20.9	21.0	21.1	21.2	21.3	21.4	21.5	21.6	21.7	21.8	21.9	22.0	22.1	22.2	22.3	22.4	22.5	22.6	22.7	22.8	22.9	23.0	23.1	23.2	23.3	23.4	23.5	23.6	23.7	23.8	23.9	24.0	24.1	24.2	24.3	24.4	24.5	24.6	24.7	24.8	24.9	25.0	25.1	25.2	25.3	25.4	25.5	25.6	25.7	25.8	25.9	26.0	26.1	26.2	26.3	26.4	26.5	26.6	26.7	26.8	26.9	27.0	27.1	27.2	27.3	27.4	27.5	27.6	27.7	27.8	27.9	28.0	28.1	28.2	28.3	28.4	28.5	28.6	28.7	28.8	28.9	29.0	29.1	29.2	29.3	29.4	29.5	29.6	29.7	29.8	29.9	30.0	30.1	30.2	30.3	30.4	30.5	30.6	30.7	30.8	30.9	31.0	31.1	31.2	31.3	31.4	31.5	31.6	31.7	31.8	31.9	32.0	32.1	32.2	32.3	32.4	32.5	32.6	32.7	32.8	32.9	33.0	33.1	33.2	33.3	33.4	33.5	33.6	33.7	33.8	33.9	34.0	34.1	34.2	34.3	34.4	34.5	34.6	34.7	34.8	34.9	35.0	35.1	35.2	35.3	35.4	35.5	35.6	35.7	35.8	35.9	36.0	36.1	36.2	36.3	36.4	36.5	36.6	36.7	36.8	36.9	37.0	37.1	37.2	37.3	37.4	37.5	37.6	37.7	37.8	37.9	38.0	38.1	38.2	38.3	38.4	38.5	38.6	38.7	38.8	38.9	39.0	39.1	39.2	39.3	39.4	39.5	39.6	39.7	39.8	39.9	40.0	40.1	40.2	40.3	40.4	40.5	40.6	40.7	40.8	40.9	41.0	41.1	41.2	41.3	41.4	41.5	41.6	41.7	41.8	41.9	42.0	42.1	42.2	42.3	42.4	42.5	42.6	42.7	42.8	42.9	43.0	43.1	43.2	43.3	43.4	43.5	43.6	43.7	43.8	43.9	44.0	44.1	44.2	44.3	44.4	44.5	44.6	44.7	44.8	44.9	45.0	45.1	45.2	45.3	45.4	45.5	45.6	45.7	45.8	45.9	46.0	46.1	46.2	46.3	46.4	46.5	46.6	46.7	46.8	46.9	47.0	47.1	47.2	47.3	47.4	47.5	47.6	47.7	47.8	47.9	48.0	48.1	48.2	48.3	48.4	48.5	48.6	48.7	48.8	48.9	49.0	49.1	49.2	49.3	49.4	49.5	49.6	49.7	49.8	49.9	50.0	50.1	50.2	50.3	50.4	50.5	50.6	50.7	50.8	50.9	51.0	51.1	51.2	51.3	51.4	51.5	51.6	51.7	51.8	51.9	52.0	52.1	52.2	52.3	52.4	52.5	52.6	52.7	52.8	52.9	53.0	53.1	53.2	53.3	53.4	53.5	53.6	53.7	53.8	53.9	54.0	54.1	54.2	54.3	54.4	54.5	54.6	54.7	54.8	54.9	55.0	55.1	55.2	55.3	55.4	55.5	55.6	55.7	55.8	55.9	56.0	56.1	56.2	56.3	56.4	56.5	56.6	56.7	56.8	56.9	57.0	57.1	57.2	57.3	57.4	57.5	57.6	57.7	57.8	57.9	58.0	58.1	58.2	58.3	58.4	58.5	58.6	58.7	58.8	58.9	59.0	59.1	59.2	59.3	59.4	59.5	59.6	59.7	59.8	59.9	60.0	60.1	60.2	60.3	60.4	60.5	60.6	60.7	60.8	60.9	61.0	61.1	61.2	61.3	61.4	61.5	61.6	61.7	61.8	61.9	62.0	62.1	62.2	62.3	62.4	62.5	62.6	62.7	62.8	62.9	63.0	63.1	63.2	63.3	63.4	63.5	63.6	63.7	63.8	63.9	64.0	64.1	64.2	64.3	64.4	64.5	64.6	64.7	64.8	64.9	65.0	65.1	65.2	65.3	65.4	65.5	65.6	65.7	65.8	65.9	66.0	66.1	66.2	66.3	66.4	66.5	66.6	66.7	66.8	66.9	67.0	67.1	67.2	67.3	67.4	67.5	67.6	67.7	67.8	67.9	68.0	68.1	68.2	68.3	68.4	68.5	68.6	68.7	68.8	68.9	69.0	69.1	69.2	69.3	69.4	69.5	69.6	69.7	69.8	69.9	70.0	70.1	70.2	70.3	70.4	70.5	70.6	70.7	70.8	70.9	71.0	71.1	71.2	71.3	71.4	71.5	71.6	71.7	71.8	71.9	72.0	72.1	72.2	72.3	72.4	72.5	72.6	72.7	72.8	72.9	73.0	73.1	73.2	73.3	73.4	73.5	73.6	73.7	73.8	73.9	74.0	74.1	74.2	74.3	74.4	74.5	74.6	74.7	74.8	74.9	75.0	75.1	75.2	75.3	75.4	75.5	75.6	75.7	75.8	75.9	76.0	76.1	76.2	76.3	76.4	76.5	76.6	76.7	76.8	76.9	77.0	77.1	77.2	77.3	77.4	77.5	77.6	77.7	77.8	77.9	78.0	78.1	78.2	78.3	78.4	78.5	78.6	78.7	78.8	78.9	79.0	79.1	79.2	79.3	79.4	79.5	79.6	79.7	79.8	79.9	80.0	80.1	80.2	80.3	80.4	80.5	80.6	80.7	80.8	80.9	81.0	81.1	81.2	81.3	81.4	81.5	81.6	81.7	81.8	81.9	82.0	82.1	82.2	82.3	82.4	82.5	82.6	82.7	82.8	82.9	83.0	83.1	83.2	83.3	83.4	83.5	83.6	83.7	83.8	83.9	84.0	84.1	84.2	84.3	84.4	84.5	84.6	84.7	84.8	84.9	85.0	85.1	85.2	85.3	85.4	85.5	85.6	85.7	85.8	85.9	86.0	86.1	86.2	86.3	86.4	86.5	86.6	86.7	86.8	86.9	87.0	87.1	87.2	87.3	87.4	87.5	87.6	87.7	87.8	87.9	88.0	88.1	88.2	88.3	88.4	88.5	88.6	88.7	88.8	88.9	89.0	89.1	89.2	89.3	89.4	89.5	89.6	89.7	89.8	89.9	90.0	90.1	90.2	90.3	90.4	90.5	90.6	90.7	90.8	90.9	91.0	91.1	91.2	91.3	91.4	91.5	91.6	91.7	91.8	91.9	92.0	92.1	92.2	92.3	92.4	92.5	92.6	92.7	92.8	92.9	93.0	93.1	93.2	93.3	93.4	93.5	93.6	93.7	93.8	93.9	94.0	94.1	94.2	94.3	94.4	94.5	94.6	94.7	94.8	94.9	95.0	95.1	95.2	95.3	95.4	95.5	95.6	95.7	95.8	95.9	96.0	96.1	96.2	96.3	96.4	96.5	96.6	96.7	96.8	96.9	97.0	97.1	97.2	97.3	97.4	97.5	97.6	97.7	97.8	97.9	98.0	98.1	98.2	98.3	98.4	98.5	98.6	98.7	98.8	98.9	99.0	99.1	99.2	99.3	99.4	99.5	99.6	99.7	99.8	99.9	100.0	100.1	100.2	100.3	100.4	100.5	100.6	100.7	100.8	100.9	101.0	101.1	101.2	101.3	101.4	101.5	101.6	101.7	101.8	101.9	102.0	102.1	102.2	102.3	102.4	102.5	102.6	102.7	102.8	102.9	103.0	103.1	103.2	103.3	103.4	103.5	103.6	103.7	103.8	103.9	104.0	104.1	104.2	104.3	104.4	104.5	104.6	104.7	104.8	104.9	105.0	105.1	105.2	105.3	105.4	105.5	105.6	105.7	105.8	105.9	106.0	106.1	106.2	106.3	106.4	106.5	106.6	106.7	106.8	106.9	107.0	107.1	107.2	107.3	107.4	107.5	107.6	107.7	107.8	107.9	108.0	108.1	108.2	108.3	108.4	108.5	108.6	108.7	108.8	108.9	109.0	109.1	109.2	109.3	109.4	109.5	109.6	109.7	109.8	109.9	110.0	110.1	110.2	110.3	110.4	110.5	110.6	110.7	110.8	110.9	111.0	111.1	111.2	111.3	111.4	111.5	111.6	111.7	111.8	111.9	112.0	112.1	112.2	112.3	112.4	112.5	112.6	112.7	112.8	112.9	113.0	113.1	113.2	113.3	113.4	113.5	113.6	113.7	113.8	113.9	114.0	114.1	114.2	114.3	114.4	114.5	114.6	114.7	114.8	114.9	115.0	115.1	115.2	115.3	115.4	115.5	115.6	115.7	115.8	115.9	116.0	116.1	116.2	116.3	116.4	116.5	116.6	116.7	116.8	116.9	117.0	117.1	117.2	117.3	117.4	117.5	117.6	117.7	117.8	117.9	118.0	118.1	118.2	118.3	118.4	118.5	118.6	118.7	118.8	118.9	119.0	119.1	119.2	119.3	119.4	119.5	119.6	119.7	119.8	119.9	120.0	120.1	120.2	120.3	120.4	120.5	120.6	120.7	120.8	120.9	121.0	121.1	121.2	121.3	121.4	121.5	121.6	121.7	121.8	121.9	122.0	122.1	122.2	122.3	122.4	122.5	122.6	122.7	122.8	122.9	123.0	123.1	123.2	123.3	123.4	123.5	123.6	123.7	123.8	123.9	124.0	124.1	124.2	124.3	124.4	124.5	124.6	124.7	124.8	124.9	125.0	125.1	125.2	125.3	125.4	125.5	125.6	125.7	125.8	125.9	126.0	126.1	126.2	126.3	126.4	126.5	126.6	126.7	126.8	126.9	127.0	127.1	127.2	127.3	127.4	127.5	127.6	127.7	127.8	127.9	128.0	128.1	128.2	128.3	128.4	128.5	128.6	128.7	128.8	128.9	129.0	129.1	129.2	129.3	129.4	129.5	129.6	129.7	129.8	129.9	130.0	130.1	130.2	130.3	130.4	130.5	130.6	130.7	130.8	130.9	131.0	131.1	131.2	131.3	131.4	131.5	131.6	131.7	131.8	131.9	

[illegible][illegible]

—

[illegible]

此乃其所以爲此也

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED (1977-1)

100-1000

2111-1
2111-2
2111-3
2111-4
2111-5
2111-6
2111-7
2111-8
2111-9
2111-10
2111-11
2111-12
2111-13
2111-14
2111-15
2111-16
2111-17
2111-18
2111-19
2111-20
2111-21
2111-22
2111-23
2111-24
2111-25
2111-26
2111-27
2111-28
2111-29
2111-30
2111-31
2111-32
2111-33
2111-34
2111-35
2111-36
2111-37
2111-38
2111-39
2111-40
2111-41
2111-42
2111-43
2111-44
2111-45
2111-46
2111-47
2111-48
2111-49
2111-50
2111-51
2111-52
2111-53
2111-54
2111-55
2111-56
2111-57
2111-58
2111-59
2111-60
2111-61
2111-62
2111-63
2111-64
2111-65
2111-66
2111-67
2111-68
2111-69
2111-70
2111-71
2111-72
2111-73
2111-74
2111-75
2111-76
2111-77
2111-78
2111-79
2111-80
2111-81
2111-82
2111-83
2111-84
2111-85
2111-86
2111-87
2111-88
2111-89
2111-90
2111-91
2111-92
2111-93
2111-94
2111-95
2111-96
2111-97
2111-98
2111-99
2111-100
2111-101
2111-102
2111-103
2111-104
2111-105
2111-106
2111-107
2111-108
2111-109
2111-110
2111-111
2111-112
2111-113
2111-114
2111-115
2111-116
2111-117
2111-118
2111-119
2111-120
2111-121
2111-122
2111-123
2111-124
2111-125
2111-126
2111-127
2111-128
2111-129
2111-130
2111-131
2111-132
2111-133
2111-134
2111-135
2111-136
2111-137
2111-138
2111-139
2111-140
2111-141
2111-142
2111-143
2111-144
2111-145
2111-146
2111-147
2111-148
2111-149
2111-150
2111-151
2111-152
2111-153
2111-154
2111-155
2111-156
2111-157
2111-158
2111-159
2111-160
2111-161
2111-162
2111-163
2111-164
2111-165
2111-166
2111-167
2111-168
2111-169
2111-170
2111-171
2111-172
2111-173
2111-174
2111-175
2111-176
2111-177
2111-178
2111-179
2111-180
2111-181
2111-182
2111-183
2111-184
2111-185
2111-186
2111-187
2111-188
2111-189
2111-190
2111-191
2111-192
2111-193
2111-194
2111-195
2111-196
2111-197
2111-198
2111-199
2111-200
2111-201
2111-202
2111-203
2111-204
2111-205
2111-206
2111-207
2111-208
2111-209
2111-210
2111-211
2111-212
2111-213
2111-214
2111-215
2111-216
2111-217
2111-218
2111-219
2111-220
2111-221
2111-222
2111-223
2111-224
2111-225
2111-226
2111-227
2111-228
2111-229
2111-230
2111-231
2111-232
2111-233
2111-234
2111-235
2111-236
2111-237
2111-238
2111-239
2111-240
2111-241
2111-242
2111-243
2111-244
2111-245
2111-246
2111-247
2111-248
2111-249
2111-250
2111-251
2111-252
2111-253
2111-254
2111-255
2111-256
2111-257
2111-258
2111-259
2111-260
2111-261
2111-262
2111-263
2111-264
2111-265
2111-266
2111-267
2111-268
2111-269
2111-270
2111-271
2111-272
2111-273
2111-274
2111-275
2111-276
2111-277
2111-278
2111-279
2111-280
2111-281
2111-282
2111-283
2111-284
2111-285
2111-286
2111-287
2111-288
2111-289
2111-290
2111-291
2111-292
2111-293
2111-294
2111-295
2111-296
2111-297
2111-298
2111-299
2111-300
2111-301
2111-302
2111-303
2111-304
2111-305
2111-306
2111-307
2111-308
2111-309
2111-310
2111-311
2111-312
2111-313
2111-314
2111-315
2111-316
2111-317
2111-318
2111-319
2111-320
2111-321
2111-322
2111-323
2111-324
2111-325
2111-326
2111-327
2111-328
2111-329
2111-330
2111-331
2111-332
2111-333
2111-334
2111-335
2111-336
2111-337
2111-338
2111-339
2111-340
2111-341
2111-342
2111-343
2111-344
2111-345
2111-346
2111-347
2111-348
2111-349
2111-350
2111-351
2111-352
2111-353
2111-354
2111-355
2111-356
2111-357
2111-358
2111-359
2111-360
2111-361
2111-362
2111-363
2111-364
2111-365
2111-366
2111-367
2111-368
2111-369
2111-370
2111-371
2111-372
2111-373
2111-374
2111-375
2111-376
2111-377
2111-378
2111-379
2111-380
2111-381
2111-382
2111-383
2111-384
2111-385
2111-386
2111-387
2111-388
2111-389
2111-390
2111-391
2111-392
2111-393
2111-394
2111-395
2111-396
2111-397
2111-398
2111-399
2111-400
2111-401
2111-402
2111-403
2111-404
2111-405
2111-406
2111-407
2111-408
2111-409
2111-410
2111-411
2111-412
2111-413
2111-414
2111-415
2111-416
2111-417
2111-418
2111-419
2111-420
21

三民書局代印

[illegible]

iii.

 $\frac{1}{2}$



0711146

for review of 0.750

NY 11703/14. 11.5.31.

100

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84



JEFFERSON COUNTY

LOCATION MAP





PLATE 1




ANDERSON LAKE

VICINITY TOPOGRAPHY

PLATE 2

SCALE IN FEET



SCALE IN METERS

ANDERSON LAKE DAM PLAN

SCALE IN FEET



PLATE 3

WATER SURFACE = 690.98
9-7-78

LAKE


Water's Edge


OF

E TOP

DAM

Assumed
Elev = 700.00








PHOTO 1: UPSTREAM VIEW OF LAKE



PHOTO 2: DOWNSTREAM VIEW FROM DAM



PHOTO 3: DOWNSTREAM FACE OF DAM AND SPILLWAY



PHOTO 4: UPSTREAM FACE OF RIGHT ABUTMENT AND SPILLWAY



PHOTO 5: DOWNSTREAM VIEW OF SPILLWAY



PHOTO 6: UPSTREAM VIEW OF SPILLWAY



PHOTO 7: EMBANKMENT NEAR SLUICE ABUTMENT, DOWNSTREAM FROM SLUICE



PHOTO 8: EMBANKMENT NEAR SLUICE ABUTMENT, DOWNSTREAM FROM SLUICE